



When the toner is positioned as shown here, the chips will have to be oriented as shown on the right hand side




HP 59 A/X  
(CF259 A/X)



HP 207 A/X  
(W2210 ..13 A/X)



HP 216 A  
(W2410 ..13 A)



HP 415 A/X  
(W2030 ..33 A/X)

